

**ELECTRICAL INSTRUCTIONS****115 V. 60 HZ. 1 PHASE**

VENT MODEL SUFFIX LETTER	MOTOR SPEED	WIRING CONNECTIONS
<b>D</b>	1550 RPM	WHITE TO L1. BLACK TO L2. SEPARATE RED AND INSULATE. SEPARATE BLUE AND INSULATE.
<b>G</b>	1300 RPM	WHITE TO L1. BLUE TO L2. SEPARATE RED AND INSULATE. SEPARATE BLACK AND INSULATE.
<b>E</b>	1050 RPM	WHITE TO L1. RED TO L2. SEPARATE BLUE AND INSULATE. SEPARATE BLACK AND INSULATE.

450009